



EMSL Analytical, Inc.

2001 East 52nd St., Indianapolis, IN 46205

Phone: (317) 803-2997 Fax: (317) 803-3047 Email: indianapolislaboratory@emsl.com

Attn: **Lars Knobloch**
Nordic Home Inspection
1614 28th Avenue South
Fargo, ND 58103

Customer ID: **NORD25**
Customer PO:
Received: **05/20/11 10:05 AM**
EMSL Order: **161107969**

Fax: Phone: (701) 566-1446
Project: **384**

EMSL Proj:
Analysis Date: **5/23/2011**


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
1-Floor Tile 161107969-0001		Brown/Green Non-Fibrous Homogeneous		98% Non-fibrous (other)	2% Chrysotile
1-Mastic 161107969-0001A		Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected

Initial report from 05/23/2011 08:23:08

Analyst(s)

Craig Nixon (2)



Richard Harding, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.
Samples analyzed by EMSL Analytical, Inc. Indianapolis, IN NVLAP Lab Code 200188-0, AZ0939, CA 2575, CO AL-15132, TX 300262